

GOVERNMENT OF KARNATAKA

Office of the  
Executive Engineer  
No. 1 Buildings Division  
S.J.P Compound, Bangalore

Telephone 22225210  
Fax 22250755  
e-mail: [cebid1@kpwd.gov.in](mailto:cebid1@kpwd.gov.in)  
[cebid1@yahoo.com](mailto:cebid1@yahoo.com)

PUBLIC WORKS DEPARTMENT

(I.S.O. 9001-2008 RECOGNIZED DIVISION)

Number: EE/BD 1/AE 5/2021 22

Dt: 08/11/2021

To

Principal,  
Sri Vidyamanya Vidya Kendra  
1<sup>st</sup> Cross, Vidyamanya Nagar,  
Andhrahalli Main Road,  
Bangalore-560 091.

Subject:

Regarding issue of Safety Certificate for School Building of  
Sri Vidyamanya Vidya Kendra, 1<sup>st</sup> Cross, Andhrahalli Main  
Road, Bangalore 560 091.

Reference: 1. Your School Letter No. SSVVK/135/2021 dated: 30-03-2021

2. Letter of M/s.Naveen Consultants, No.13098, 2<sup>nd</sup> Floor,  
2<sup>nd</sup> Cross, Ashoka Nagara, (Behind BMS Engineering  
College Hostel), Basavanagudi, Banashankari 1<sup>st</sup> Stage,  
Bangalore-560050.


3. Letter No. 538, dt: 25-10-2021 of the Assistant Executive  
Engineer, No.4, Buildings Sub Division, Bangalore.

\*\*\*\*\*

With reference to the above subject, in your letter of reference (1), you requested to issue Safety Certificate for School Building of Sri Vidyamanya Vidya Kendra, 1st Cross, Andhrahalli Main Road, Bangalore 560 091. The said Building is having Total Ground and Two Floor Building, (Ground, First and Second Floor) built up area is as shown hereunder. The said Building is comprised with extent of total 4634.00 Sq. Meters.

For SREE DHAMA SEVA TRUST

*Bhava S.R.*  
Secretary



SRI VIDYAMANYA VIDYA KENDRA

*[Signature]*  
PRINCIPAL

The said Institution filed the following necessary records alongwith the Letter.

1. Annexure-'C' as per NBC
2. Plans of Structural frame work of columns, Beams, slabs Layouts
3. Approved Plan.
4. Reports issued regarding conducted Non Destructive test, Rebound hammer and Pulse velocity test.


Continuing, on dated 04-08-2021, alongwith Assistant Executive Engineer, No 4 Buildings Sub Division, the building of the said School was inspected. During this time, the Principal of the said School, M/s. Geo-Syndicate Engineers & Consultants, No. 26, 3<sup>rd</sup> Main, Jnanaganga Nagar, Jnanabharathi, Bangalore-560 056, having checked the Design and M/s. Naveen Consultants were present.

Continuing, Geo-Syndicate Engineers & Consultants, No. 26, 3<sup>rd</sup> Main, Jgnanaganga nagar, Jnanabharathi, Bangalore-560 056 issued Ultrasonic Pulse Velocity Test and Rebound Hammer Test, Structural Stability Certificate, Structural Design and M/s. Naveen Consultants issued Annexure-C in accordance with National Building Code of 2016. On dated 29-03-2021, Chief Fire Officer, Bangalore West, Sheshadri Road, Bangalore, issued Compliance Report and Fire Safety Recommendation Letter.

Thereafter, the Members of School Management present and alongwith Dr. Anandakumar B.G., Chartered Engineer-M-173535, made inspection of Inner Part and Outer Part of the Building, and that the said Building is having Ground and Two Floor, (Ground First and Second Floor), consisting of each 53 Rooms and Dr. Anandakumar B.G, Chartered Engineer verified Building Design and issued

For SREE DHAMA SEVA TRUST

*Bhava S. R.*  
Secretary



SRI VIDYAMANYA VIDYA KENDRA

*[Signature]*  
PRINCIPAL



It is noted that from the building has been constructed as per Criteria of National Building Code of India-2016.

M/s. Naveen Consultants, Bangalore, certified and filed Annex 'C' Certificate in accordance with Structural Stability certificate and national building code. Considered the above points and information issued by Structural Engineer, verified the building alongwith the Executive Engineer, No.4, Building Sub-Division, Bangalore, found that the building is safety.

Structural frame work, all floors of the School Building and important parts of the Building were verified. At this time, do not found either any cracks and unequal settlements in the Building.

In the background of the above points, opined that the said Building is Safe.

Responsibility of doing maintenance of the said building is that of the said School and this Certificate is subjected to the condition of withdrawing any time. The said Certificate may be utilized for the purpose of renewing the Recognition of the School Building of Sri. Vidyamanya Vidyakendra, 1<sup>st</sup> Cross, Vidyamanya Nagar, Anandhalli Main Road, Bangalore 560 091, for the year 2021-22.

Yours faithfully,

SD/-

Executive Engineer,  
No.1, Buildings Division, Bangalore.

Translated from Kannada to English by

*[Handwritten signature]*  
S. D. S. S. S.  
2021  
#992116333

*[Circular stamp]*  
SRI VIDYAMANYA VIDYA KENDRA  
1st Cross, Vidyamanya Nagar,  
Anandhalli Main Road,  
Bangalore - 560 091

For SREE DHAMA SEVA TRUST  
FOR SRI

*[Handwritten signature]*  
Secretary

2022

SRI VIDYAMANYA VIDYA KENDRA  
*[Handwritten signature]*  
PRINCIPAL

4. Non Destructive test, Rebound hammer and Pulse velocity test ಗಳನ್ನು ನಡೆಸಲಾಗಿರುವ  
ಫಲವಿವರಣೆ  
ಮುಂದುವರಿದಂತೆ, ದಿನಾಂಕ 04-09-2021 ರಂದು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ  
ಇಂಜಿನಿಯರ್, ನಂ.4 ಕಟ್ಟಡಗಳ ಉಪವಿಭಾಗ ರವರೊಂದಿಗೆ ಸದರಿ ಶಾಲೆಯ ಕಟ್ಟಡವನ್ನು  
ಪರಿಶೀಲಿಸಲಾಯಿತು. ಈ ಸಮಯದಲ್ಲಿ ಸದರಿ ಶಾಲೆಯ ಪ್ರಾಂಶುಪಾಲರು, ವಿನ್ಯಾಸ ಪರಿಶೀಲಿಸಿದ  
M/s Geo-Syndicate Engineers & Consultants No. 26, 3<sup>rd</sup> Main, Jnanaganga Nagar,  
Jnanabharathi, Bangalore -560 056 ಮತ್ತು M/s. Naveen Consultants ರವರುಗಳು ಹಾಜರಿವುದು.

ಮುಂದುವರಿದು, Geo-Syndicate Engineers & Consultants, No. 26, 3<sup>rd</sup> Main, Jnanaganga  
Nagar, Jnanabharathi, Bangalore -560 056 ರವರು Ultrasonic Pulse Velocity Test and Rebound  
Hammer Test, Structural Stability Certificate, Structural Design ಗಳನ್ನು ನೀಡಿರುತ್ತಾರೆ ಮತ್ತು  
National Building Code of 2016 ರನ್ವಯ Annexure C ಅನ್ನು M/s. Naveen Consultants ರವರು  
ನೀಡಿರುತ್ತಾರೆ. ದಿನಾಂಕ 29-03-2021 ರಲ್ಲಿ Chief Fire Officer, Bangalore West, Sheshadri Road,  
Bangalore ರವರು Compliance Report and Fire Safety Recommendation ಪತ್ರವನ್ನು ನೀಡಿರುತ್ತಾರೆ.

ನಂತರ ಹಾಜರಿವಿದ್ದ ಶಾಲಾ ಆಡಳಿತ ಮಂಡಳಿ ಸದಸ್ಯರು ಹಾಗೂ Dr. Anandakumar B.G,  
Chartered Engineer M 1735535 ರವರೊಂದಿಗೆ ಕಟ್ಟಡದ ಒಳಭಾಗ ಹಾಗೂ ಹೊರಭಾಗವನ್ನು  
ಪರಿಶೀಲಿಸಿ ಮಾಡಲಾಗಿ ಸದರಿ ಕಟ್ಟಡವು ನೆಲ ಮತ್ತು ಎರಡು ಅಂತಸ್ತು ಹೊಂದಿದ್ದು, (ನೆಲ ಮೊದಲನೇ  
ಮತ್ತು ಎರಡನೇ ಮಹಡಿ) ತಲಾ 53 ಕೊಠಡಿಗಳನ್ನು ಒಳಗೊಂಡಿರುತ್ತದೆ ಹಾಗೂ Dr. Anandakumar  
B.G Chartered Engineer ರವರು ಕಟ್ಟಡ ವಿನ್ಯಾಸವನ್ನು ಪರಿಶೀಲಿಸಿ National Building Code of India -  
2016 ರ ಮಾನದಂಡದಂತೆ ನಿರ್ಮಿಸಲಾಗಿದೆ ಎಂದು ಕಂಡುಬಂದಿರುತ್ತದೆ ಎಂದು ದೃಢೀಕರಣ ಪತ್ರ  
ನೀಡಿರುತ್ತಾರೆ.

Structural Stability certificate and national building code, ರನ್ವಯ Annex 'C'  
certificate ಅನ್ನು M/s Naveen Consultants, Bangalore ದೃಢೀಕರಿಸಿ ಸಲ್ಲಿಸಿರುತ್ತಾರೆ. ಮೇಲ್ಕಂಡ  
ಆರೋಪವು ಹಾಗೂ ವ್ಯಕ್ತರಲ್ಪಡಬಹುದಾದ ರವರು ನೀಡಿರುವ ಮಾಹಿತಿಯನ್ನು ಪರಿಗಣಿಸಿ, ಸಹಾಯಕ  
ಕಾರ್ಯಪಾಲಕ ಅಜಿಯಂತರರು, ನಂ.4, ಕಟ್ಟಡಗಳ ಉಪ-ವಿಭಾಗ, ಬೆಂಗಳೂರು ರವರೊಂದಿಗೆ  
ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡವೂ ಸುರಕ್ಷಿತವಾಗಿವೆ ಎಂದು ಕಂಡು ಬಂದಿರುತ್ತದೆ.

ಕಟ್ಟಡದ Structural frame work, ಶಾಲಾ ಕಟ್ಟಡದ ಎಲ್ಲಾ ಮಹಡಿಗಳು ಹಾಗೂ ಪ್ರಮುಖ  
ಭಾಗವನ್ನು ಪರಿಶೀಲಿಸಲಾಯಿತು ಈ ಸಮಯದಲ್ಲಿ ಕಟ್ಟಡದಲ್ಲಿ ಯಾವುದೇ ಬರುಕುಗಳಾಗಲಿ ಮತ್ತು  
Unequal settlement ಗಳಾಗಲಿ ಕಂಡು ಬಂದಿರುವುದಿಲ್ಲ.

For SREF DHAMA SEVA TRUST

Bharat R.  
Secretary

[Signature]  
SRI VIDYAMANYA VIDYA KENDRA  
PRINCIPAL



ಈ ಮೂಲಕ ಎಲ್ಲಾ ಅಂಶಗಳ ಹಿನ್ನೆಲೆಯಲ್ಲಿ ಸದರಿ ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿದೆ ಎಂದು  
ಆಯಾ ಅಧಿಕಾರಿಯರು

ಸದರಿ ಕಟ್ಟಡವನ್ನು ನಿರ್ವಹಣೆ ಮಾಡುವ ಬದಾಯಿಯು, ಸದರಿ ಶಾಲೆಯೊಳಗಿದ್ದುಂತ್ತದೆ.  
ಹಾಗೂ ಈ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಯಾವುದೇ ಕಾರಣದಿಂದಲೂ ಹಿಂಪಡೆಯುವ ಜರತ್ತಿಗಿರಲಿಲ್ಲವೆಂದು ಸದರಿ  
ಶಾಲೆಯ ವ್ಯವಸ್ಥಾಪಕರು 2021-22 ನೇ ಸಾಲಿನ ಶ್ರೀ ವಿಜಯಮಾನ್ಯ ವಿದ್ಯಾಕೇಂದ್ರ, 'ನೇ ಕ್ರಾಸ್', ವಿಜಯಮಾನ್ಯ  
ನಗರ, ಅಂದ್ರಹಳ್ಳಿ ಮುಖ್ಯ ರಸ್ತೆ, ಬೆಂಗಳೂರು 560 091 ಶಾಲಾ ಕಟ್ಟಡದ ಮಾನ್ಯತೆಯನ್ನು  
ನವೀಕರಿಸಿಕೊಳ್ಳುವ ಉದ್ದೇಶಕ್ಕೆ ಮಾತ್ರ ಬಳಸಬಹುದಾಗಿರುತ್ತದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

*Kumar*

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು  
ನಂ.1 ಕಟ್ಟಡಗಳ ವಿಭಾಗ, ಬೆಂಗಳೂರು

For SRE DHAMA SEVA TRUST

*Bhara R.*  
Secretary

SRI VIDYAMANYA VIDYA KENDRA  
*[Signature]*  
PRINCIPAL